Operator: PEOPLES GAS LIGHT AND COKE CO.	Operator ID#: 15329
Inspection Date(s): 9/23/2014 Man Days: 1	
Inspection Unit: Joliet	
Location of Audit: Joliet	
Exit Meeting Contact: Scott Monday	
Inspection Type: Standard Inspection - Field Audit	
Pipeline Safety Representative(s): Matt Smith	
Company Representative to Receive Report: Tom Webb	
Company Representative's Email Address: TJWebb@peoplesgasdelivery.com	

Headquarters Address Information:	200 E. Randolph Street	
	Chicago, IL 60601	
	Emergency Phone#:	
	Fax#:	
Official or Mayor's Name:	Jodi Caro	Willard Evans
	Phone#: (000) 000-0000	Phone#: (000) 000-0000
	Email:	Email:
Inspection Contact(s)	Title	Phone No.
Scott Monday	Supervisor Gas Control Operations	(815) 724-2605

	CUSTOMER METER & REGULATOR	Status
Category Comment:		
The segment of pipeline i	nspected does not contain customer service lines nor customer meters or regulators. The pipeline is strictly	a transmission pipeline.
[192.353(a)]	Is the customer meter and regulator installed in a readily accessible location and protected from corrosion and other damage, including if installed outside a building, vehicular damage that may be anticipated?	Not Applicable
[192.355(b)(1)]	Is the customer regulator vent rain and insect resistant?	Not Applicable
[192.355(b)(2)]	Is the customer regulator vent located where gas from the vent escapes freely into the atmosphere and away from building openings?	Not Applicable
[192.355(b)(3)]	Is the vent protected from damage caused by submergence in areas of flooding?	Not Applicable
[192.357(a)]	Is the customer meter and regulator installed to minimize anticipated stresses upon connecting piping?	Not Applicable

Unless otherwise noted, all code references are to 49CFR Part 192.

If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.357(d)]	Is a customer regulator that might release gas vented to the outside atmosphere?	Not Applicable
[192.359(a)]	Is the meter operating pressure within the allowable limits of the meter case rating?	Not Applicable
[192.365(a)]	Is the service line valve upstream of the regulator or meter?	Not Applicable
[192.365(c)]	Is the underground service line valve located in a curb box or standpipe that allows for ready operation?	Not Applicable
[192.727(d)][192.727(d)]	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?	Not Applicable
CATHODIC PROTECTION		Status
[192.463(a)]	Is the applicable cathodic protection criteria contained in Appendix D of this part being followed?	Satisfactory
[192.465(a)]	Were pipe to soil readings taken?	Satisfactory

General Comment:

Cathodic protection levels were inspected at the following locations (yellow is the 42" pipeline and red is the 30" pipeline):

34701 S. Danilson Rd.

- -1.33 yellow
- -1.35 red

17000 block W. Bell Rd.

- -1.36 red
- -1.33 yellow

Ballou Rd. Mile post 187

- -1.37 red
- -1.36 yellow

18000 block W. Town Line Rd.

- -1.34 yellow
- -1.38 red

17000 block W. Kahler Rd.

- -1.36 yellow
- -1.36 red

[192.465(b)]	Were rectifier installations inspected?	Not Checked
General Comment:		•
The rectifier was not ac	cessible and therefore not inspected during this audit.	
[192.465(a)]	Were isolated mains/services tested?	Not Applicable
General Comment:		
This segment of transm	ission pipeline does not contain isolated sections.	
[192.465(c)]	Were critical/non critical bonds tested?	Satisfactory
General Comment:		

	ipeline was -1.40 and the yellow -1.33. The bond read 3.5 mv.	
[192.467(a)]	Is electrical isolation provided by use of insulated meter spud, valve, union, or flange?	Satisfactory
192.467(c)]	Were casings installations tested for electrical isolation?	Not Checked
General Comment:		
The segment inspected o	lid not contain casings.	
192.479(a)]	Is the above ground piping coated or painted as required?	Satisfactory
192.479(c)]	Is the pipeline free of corrosion or pitting?	Satisfactory
	DAMAGE PREVENTION	Status
Category Comment:		
Pipeline markers were in	spected beginning south of the Joliet operating center following the pipeline path and ending in the 34000 block	k of S. Danilson Road.
192.614]	Does the operator have a valid notification of planned excavation activities?	Not Checked
General Comment:		
The audit did not consist	of reviewing damage prevention locates.	
[265.40(a)]	Did the operator complete the locating activities in the specified timeframe?	Not Checked
General Comment:		
The audit did not consist	of reviewing damage prevention locates.	
[192.614(c)(5)]	Were temporary markings made in accordance with the operator's Operation and Maintenance Manual?	Not Checked
General Comment:	·	
The audit did not consist	of reviewing damage prevention locates.	
[192.707(a)(1)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located at each crossing of a public road and railroad?	Satisfactory
192.707(a)(2)]	Are line markers placed and maintained as close as practical over each buried main and transmission line located wherever necessary to identify the location of the transmission line or main to reduce the possibility of damage or interference?	Satisfactory
192.707(c)]	Are line markers placed and maintained as close as practical over each main and transmission line located above ground?	Satisfactory
[192.707(d)(1)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line	Satisfactory

	(or name of gas transported) Pipeline" all of which, except for markers in heavily developed urban areas, must be in letters at least 1 inch (25 millimeters) high with ¼ inch (6.4 millimeters) stroke?	
[192.707(d)(2)]	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The name and phone number (including area code) of the operator where the operator can be reached at all times?	Satisfactory
PRESSURE	ELIMITING AND REGULATING DEVICES (MECHANICAL)	Status
Category Comment: The audit did not consist of ins not conducted at this time.	specting pressure limiting and regulating devices. The Manhattan Station was observed, but a detailed re	eview of the devices was
[192.739(a)(4)]	Was each pressure limiting station, relief device (except rupture discs), and pressure regulating station and its equipment subjected at intervals not exceeding 15 months, but at least once each calendar year, to inspections and tests to determine that it is properly installed and protected from dirt, liquids, or other conditions that might prevent proper operation.?	Not Checked
[192.317(b)]	Is each above ground transmission line or main protected from accidental damage by vehicular traffic or other similar causes?	Not Checked
[192.741(a),192.741(c)]	Were telemetering and/or recording gauges inspected for abnormally high or low pressure indications?	Not Checked
[192.743(a)]	Is overpressure protection provided on the pipeline down stream of the take point?	Not Checked
[192.199(d)]	Were the pressure relief or pressure limiting devices inspected to determine if the support was made of noncombustible material?	Not Checked
[192.199(e)]	Were the pressure relief or pressure limiting devices inspected to determine if the discharge stacks, vents, or outlet ports were designed to prevent accumulation of water, ice, or snow, and located where gas can be discharged into the atmosphere without undue hazard?	Not Checked
[192.199(h)]	Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?	Not Checked
VALVE MAINTENANCE		Status
[192.747(a)]	Were the valves readily accessible and was the operator able to access the valve with the appropriate valve wrench?	Not Checked
General Comment:		
Valves were not inspected dur	ing this audit.	
[192.179(c)]	If blow down activities were observed, were the blow down valves properly sized to allow the transmission pipeline to vent as rapidly as practicable and did the blow down vent freely to atmosphere away from any hazards?	Satisfactory
General Comment:	·	

	ODORIZATION OF GAS	Status
Category Comment:		
Odorization was not insp	ected during this audit.	
[192.625(a)]	Was the odor intensity level readily detectable at or below 1/5th LEL?	Not Checked
[192.625(e)]	Was the Odorization equipment and tank levels inspected?	Not Checked
[192.625(f)]	Was the operator's equipment calibrated as required?	Not Checked
	TRANSMISSION	Status
Category Comment:		
Transmission valves and	pre-tested pipe was not inspected during this audit.	
[192.179(b)(1)]	Are transmission valves protected from tampering or damage?	Not Checked
[192.745(a)]	Were the valves inspected accessible?	Not Checked
[192.719(a)]	Is pre-tested transmission pipe inventory maintained for use in an emergency?	Not Checked
MARKING OF MATERIAL		Status
Category Comment:		
Staff did not inspect man	king of material during this audit.	
[192.63(a)]	Does the operator's components and pipe contain the required markings?	Not Checked
OPERATOR QUALIFICATION		Status
Was a PHMSA Form 15 Operator Qualification Field Inspection Protocol Form completed?		No